



RBI - Technical Services

Reg. No. 290202107599 [MICRO/SERVICES]
Road - Building - Irrigation Material Testing Laboratory
NABL Accredited Laboratory as per ISO/IEC 17025-2005
Managing Director - P. Munikrishnappa, B.E., (Civil) M.I.E. K.E.S.
ISO 9001 - 2015 Certified

Date:

PMC Report

Name of the work : Improvements to Roads, Drains and Drilling Borwells in ward no. 07 & 08 of Kodigehalli Sub-Division of Byatarayanapura Division, under P3106 Nagarathana works.

Name of the Client : Executive Engineer, Byatarayanapura Division, BBMP-Bangalore.

Contractor/Agency : Sri. G.N Ramesh

Reference : Work order No:- BBMP/EE/BTP/WO/262/16-17 dt:31.03.2017

Date of Inspection :

Status of Bill : 2nd and Part bill

In the presence of : Sri. H. Ranganath, AEE, Kodigehalli Sub Division, BBMP Bangalore.

: Sri. Mohammad Liyaqut Ali, AE. Ward No. 08, BBMP Bangalore.

: Sri. N.D Puspallatha, AE. Ward No. 07, BBMP Bangalore.

: Sri. Avinash, Site Engineer, RBI-Technical Services.

SL.No	Description of the item		Comments/observations
1	Removing B.S.Slab Drain complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
2	Refixing stone slabs of drains and pointing in CM (1:3) complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
4	Earth work excavation....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
3	Providing granite slabs complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
54	Dismantling of existing structures complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily



RBI - Technical Services

Reg. No. 290202107599 [MICRO/SERVICES]
Road - Building - Irrigation Material Testing Laboratory
NABL Accredited Laboratory as per ISO/IEC 17025-2005
Managing Director - P. Munikrishnappa, B.E., (Civil) M.I.E. K.E.S.
ISO 9001 - 2015 Certified

55	Dismantling of existing structures complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
50	Providing and laying in position of PCC of mix 1:4:8 etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
60	Providing and laying in position of PCC of mix 1:2:4 etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
57	Providing and constructing granite/trap etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
59	Providing Ruled pointing....etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
E6	Providing and fixing 10cm thick etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
E4	Providing and fixing 20cm thick etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
5	Scarifying existing stone metal etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
6	Providing and laying WMM etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
8	Providing and applying primer coat etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
11	Providing and laying BM etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
10	Providing and applying Tack coat etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
12	Providing and laying BC etc complete	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily

[Signature]
 # 2243, 4th 'A' Cross, Hampinagar, Vijayanagar 2nd State, Bengaluru - 560 104
 H-08

[Signature] N.D
 AE (M)

[Signature]
 Assistant Executive Engineer
 Bangalore Mahanagara Palika
 Bangalore - 560 092

Cell : 9448352709 Email : rbitc2@gmail.com



RBI - Technical Services

Reg. No. 290202107599 [MICRO/SERVICES]

Road - Building - Irrigation Material Testing Laboratory

NABL Accredited Laboratory as per ISO/IEC 17025-2005

Managing Director - P. Munikrishnappa, B.E., (Civil) M.I.E. K.E.S.

ISO 9001 - 2015 Certified

63	Providing and fixing pre cast solid cement kerb stone....etc complete		The Billed Quantities are certified and Quality of work Executed Satisfactorily
64	Providing and applying ready mix priming etc complete		The Billed Quantities are certified and Quality of work Executed Satisfactorily
65	Providing and applying spry painting in two coats etc complete		The Billed Quantities are certified and Quality of work Executed Satisfactorily
E5	Providing and fixing MS Grating 260X260mm....etc complete		The Billed Quantities are certified and Quality of work Executed Satisfactorily
13	Loading and unloading of stone boulder....etc complete		The Billed Quantities are certified and Quality of work Executed Satisfactorily
1	Removing B.S.Slab Drain complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
2	Refixing stone slabs of drains and pointing in CM (1:3) complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
4	Earth work excavation....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
3	Providing granite slabs complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
5	Scarifying existing stone metal layer up to 75mm thick complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
6	Providing and laying WMM complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
7	Cleaning the existing WBM complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
8	Providing and applying primer coat complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily

[Signature]

[Signature] N.D. AEL

[Signature] Assistant Executive Engineer

2243, 4th 'A' Cross, Hampinagar, Vijayanagar 2nd State, Bengaluru - 560 104, Tel: 980-2330857

Cell : 9448352709 Email : rbitc2@gmail.com

Bangalore Mahanagara Palike Bangalore - 560 092



RBI - Technical Services

Reg. No. 290202107599 [MICRO/SERVICES]
Road - Building - Irrigation Material Testing Laboratory
 NABL Accredited Laboratory as per ISO/IEC 17025-2005
 Managing Director - P. Munikrishnappa, B.E., (Civil) M.I.E. K.E.S.
ISO 9001 - 2015 Certified

9	Cleaning the existing block topped surface complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
10	Providing and applying tack coat complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
12	Providing and laying BC complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
13	Lead of disposal complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
40	Dismantling plastering and removing the debris....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
41	Providing 12mm thick....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
42	Providing 20mm thick....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
43	Providing lime rendering complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
44	Providing 18mm thick....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
45	Providing and applying two coats....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
46	Providing and finishing external walls....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
47	Providing and applying enamel metal paint....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
26	Providing Honne wood frames....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily

M. N. D.

M. N. D.

Devi

2243, 4th 'A' Cross, Hampinagar, Vijayanagar 2nd State, Bengaluru - 560 104. Tel: 080-23300857

Cell : 9448352709 Email : rbitc2@gmail.com

Assistant Executive Engineer
 Kodigehalli Sub Division
 Bruhat Bangalore Mahanagara Palika
 Bangalore - 560 092



RBI - Technical Services

Reg. No. 290202107599 [MICRO/SERVICES]
Road - Building - Irrigation Material Testing Laboratory
NABL Accredited Laboratory as per ISO/IEC 17025-2005
Managing Director - P. Munikrishnappa, B.E., (Civil) M.I.E. K.E.S.
ISO 9001 - 2015 Certified

27	Providing and fixing in position fully paneled hone wood....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
28	Providing and fixing in position fully paneled hone wood....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
29	Painting of wood surface....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
30	Providing and applying painting two coat....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
31	Dismantling weather proof course....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
32	Providing and applying integral cement based water proofing....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
33	Providing and fixing on wall surface....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
3	Providing Granite slabs....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
4	Earth work excavation....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
14	Earth work in surface excavation....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
E2	Construction of GSB....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
6	Providing and lying WMM....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
E1	Providing and laying of hot applied thermoplastic compound....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily



RBI - Technical Services

Reg. No. 290202107599 [MICRO/SERVICES]

Road - Building - Irrigation Material Testing Laboratory

NABL Accredited Laboratory as per ISO/IEC 17025-2005

Managing Director - P. Munikrishnappa, B.E., (Civil) M.I.E. K.E.S.

ISO 9001 - 2015 Certified

E1	Providing and laying of hot applied thermoplastic compound....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
E1	Providing and laying of hot applied thermoplastic compound....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
E1	Providing and laying of hot applied thermoplastic compound....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
13	Lead of disposal....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
1	Removing B.S.Slab Drain complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
2	Refixing stone slabs of drains and pointing in CM (1:3) complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
4	Earth work excavation....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
3	Providing granite slabs complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
5	Scarifying existing stone metal layer up to 75mm thick....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
6	Providing and laying WMM complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
7	Cleaning the existing WBM complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
8	Providing and applying primer coat complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
9	Cleaning the existing black topped surface complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily

[Signature]

[Signature] M. N. P.

[Signature] Assistant Executive Engineer

2243, 4th 'A' Cross, Hampinagar, Vijayanagar 2nd State, Bengaluru - 560 104 Tel: 9448352709

Cell : 9448352709 Email : rbitc2@gmail.com

Kodigehalli Sub 23000857

Bangalore Mahanagara Palika

Bangalore - 560 004



RBI - Technical Services

Reg. No. 290202107599 [MICRO/SERVICES]

Road - Building - Irrigation Material Testing Laboratory

NABL Accredited Laboratory as per ISO/IEC 17025-2005

Managing Director - P. Munikrishnappa, B.E., (Civil) M.I.E. K.E.S.

ISO 9001 - 2015 Certified

10	Providing and applying tack coat complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
11	Providing and laying BM complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
12	Providing and laying BC complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
E1	Providing and laying of hot applied thermoplastic compound complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily
13	Lead of disposal....complete, etc	:	The Billed Quantities are certified and Quality of work Executed Satisfactorily

Munish
HOB

Asst. Eng. N.D
AE (u2)

Asst. Eng.
Assistant Executive Engineer Authorized Signatory
Kodigehalli Sub Division
Bruhat Bangalore Mahanagara
Bangalore - 5

Proprietor
Proprietor